	Type	#	Hits	Search Text	DBs	Time Stamp	Comment	Error Definition	Err
.	BRS	L.1		(electrical or electronic) same (cabinet or rack) same (door same latch) same (temperature same trigger)	US- PGPUB , USPAT , EPO; JPO; DERWE	2005/01/1 1 08:21			
2	BRS	1.2	0	(electrical or electronic) and (cabinet or rack) same (door same latch) same (temperature same trigger)	US-PGPUB; USPAT; CEPO; JPO; DERWE	2005/01/1 1 08:27			
3	BRS	L13	0	(electrical or electronic) and (cabinet or rack) and (door same latch) same (temperature same trigger)	US-PGPUB CUSPAT COSPAT COSP	2005/01/1 1 08:24			

	Type	# "I	Hits	Search Text	DBs	Time Stamp	Comment	Error Definition	Err
4	BRS	1.4	1	(cabinet or rack) and (door same latch) same (temperature same trigger)	US- PGPUB CUSPAT COSPO; JPO; DERWE NT	2005/01/1 1 08:22			
5	BRS	1.5	ω	(door same latch) same (temperature same trigger)	US-PGPUB , USPAT , EPO; JPO; DERWE NT	2005/01/1			
9	BRS	ГБ	Ō	(door and latch) same (temperature same trigger)	US- PGPUB CUSPAT FPO; JPO; DERWE NT	2005/01/1			

	Type	1 #	Hits	Search Text	DBs	Time Stamp	Comment	Error Definition	Err
7	BRS	L7	16	(door and latch) same (temperature and trigger)	US- VSPAT VSPAT FEPO; JPO; DERWE	2005/01/1 1 08:23			
&	BRS	F 8	1.5	(electrical or electronic) and (cabinet or rack) and (door same latch) same (temperature same sensor)	PUB PAT D; SWE	2005/01/1 i 08:27			
6	BRS	L9	25	(electrical or electronic) and (cabinet or rack) and (door and latch) same (temperature and sensor)	PUB	2005/01/1		-	

	Туре	# "I	Hits	Search Text	DBs	Time Stamp	Comment	Error Definition	Err
10	BRS	L10	10	9 not 8	US- PGPUB ; USPAT ; EPO; JPO; DERWE NT	2005/01/1 1 08:27			
11	BRS	111	999	cooling and (cabinet or rack)and (door same (temperature same (sensor or trigger)))	US- PGPUB ; USPAT ; EPO; JPO; DERWE NT	2005/01/1 1 08:28			